

175 Cabot Street – Suite 210 Lowell, MA 01854 USA www.cspi.com NASDAQ: CSPI

### How to upgrade Linux DBLv5 to version 5.0.7?

## Model:

N/A

# **Software:**

DBLv5

## **Operating System:**

Supports Linux Operating System.

## **Information:**

#### **Software Installation:**

1. Download the 5.0.7 software release for Linux using one of the following links.

### Fedora Distributions (RHEL, CentOS):

myri\_dbl-5.0.7.53814.PHX\_1ea770d91.rhel.phx-6374.x86\_64.rpm

#### **Debian Distributions (Ubuntu):**

myri\_dbl-5.0.7.53814.PHX\_1ea770d91.phx-6374.x86\_64.tgz

1. Download the Phoenix tools package.

phx-tools-1.32.tar.gz

2. As root, uninstall any previous versions of CSPi's Myricom software.

#### **Fedora Distributions:**

\$ sudo yum remove myri dbl

### **Debian Distributions:**

\$ sumo rm -r/opt/dbl

3. Install the Tools package

# tar xzvf phx-tools-1.32.tar.gz

4. Update the firmware to version 2.0.5

#cd phx-tools-1.32

#### #bin/phx-replace-eeprom fw-8E-2S-2.0.5. bin

Preparing to reprogram firmware on unit 0 (3:0.0)

Programming EEPROM with fpga image contained in fw-8E-2S-2.0.5.bin len=16006908

Please do not turn off power while flash is being programmed.

Do you want to continue (enter yes)? Yes

Loading....################################ | 100%

Verifying..################################ | 100%

Flash verification succeeded!

Power cycle the system to enable the new firmware.

- 5. After the programming is complete, you must power-cycle (shutdown) the server. A reboot/restart is not sufficient. When the FGPA is power-cycled it will load the new firmware.
- 6. Confirm that the new firmware, version 2.0.5, was loaded.

```
#cd phx-tools-1.32

#bin/myri_info
Pci-dev at 01:00.0 vendor: product (Rev) =lc09:4258(01)
Behind bridge root-port: 00:01.0 8086:0c01 (x8.3/x8.3)

Myri-10G-PCIE-8E – Link x8

MAC=00:60:dd:43:52:f0
SN=490333
PC=10G-PCIE3-8E-2S
PN=09-04669
BOM=A

Firmware:
```

Version 2.0.5
7. Install the DBLv5 driver.

### Fedora Distributions:

\$ sudo yum —y install ./myri\_dbl-5.0.7.53814. PHX\_1ea770d91.rhel.phx-6374.x86\_64.rpm Building PHOENIX dbl driver for 3.10.0-327.13.1.e17.x86\_64 in /opt/dbl/src

DBL driver in /opt.dbl/sbin

Created symlink from /etc/stemd/system/default.target.wants/myri\_start\_stop.service to /etc/system/system/myri\_start\_stop.service.

#### **Debian Distributions:**

\$ cd/opt

\$ sudo tar xzvf ./myri\_dbl-5.0.7.53814.PHX\_1ea770d91.phx-6374.x86\_64.tgz

\$ mv myri\_dbl-5.0.7.53814.PHX\_1ea770d91.phx-6374.x86\_64 dbl

\$ cd /opt/dbl

\$ sudo sbin/rebuild.sh

Building PHOENIX dbl driver for 3.10.0-327.13.1.e17.x86\_64 in /opt/dbl/src DBL driver in /opt/dbl/sbin

For Ubuntu servers that use system (15.04+) you can also perform the following steps to start the driver automatically.

\$ sudo cp/opt/dbl/sbin/myri start stop .service /etc/system/system

\$ sudo systemctl enable myri\_start\_stop.service

\$ sudo systemctl start myri\_start\_stop.service

### For additional information, please refer to the following documentation:

The last chapter of the User Guide has details regarding limitations and restrictions in this release. DBLv5

Release Notes: CHANGES.txt

DBLv5 User Guide: DBLv5\_UserGuide.pdf

DBLv5 Reference Manual: DBLv5\_API\_ReferenceManual.pdf

**Technical Support:** 

Please contact us for additional assistance.

Email: support@cspi.com

Support Portal: <a href="http://www.cspi.com/en/myricom-product-support">http://www.cspi.com/en/myricom-product-support</a>

Revision	<u>Date</u>	<u>Change</u>
1	7/5/2016	Initial Draft
2	8/19/2016	Feedback Edits